



TPE331 Engine Performance Ratings

| Model | Thermodynamic Rating | | |
|-----------------|----------------------|--------|------|
| | (SHP) | (ESHP) | RPM |
| Pre-Century | 575 | 605 | 2000 |
| -1/-2 (Century) | 715 | 755 | 2000 |
| -3U | 840 | 904 | 2000 |
| -5 | 840 | 904 | 1591 |
| -6 | 840 | 904 | 2000 |
| -8/-9 | 865 | 907 | 2000 |
| -10/-10T | 1000 | 1045 | 1591 |
| -10A/AV/UA/N | 1000 | 1045 | 2000 |
| -11U | 1000 | 1045 | 1591 |
| -12U | 1100 | 1151 | 1591 |
| -12B | 1100 | 1151 | 2000 |
| -14A/B/F | 1645 | 1712 | 1540 |
| -15AW | 1645 | 1705 | 1390 |
| -14GR/HR | 1759 | 1822 | 1522 |

For more information, contact:

Executive Aircraft Maintenance

Scottsdale, AZ

Anchorage, AK

Glendale, AZ

www.eamaz.com

Toll-Free: 866.991.0905

Tel: 480.991.0900

Fax: 480.991.3067